



SRT Chart 08-02-2010

Hodyon #	Description	Diagnosis SRT	R & R SRT	Admin	Notes
55-8008	24mm Radiator	0.25 hrs	1.25 hrs	\$22.00	\$22 allowance for coolant
55-8009	Dynasys Generator	0.50 hrs	2.00 hrs	\$0.00	
55-8047	Generator Pulley, 107.5mm	0.25 hrs	0.50 hrs	\$0.00	
55-8055	Dayco Tensioner #89357	0.25 hrs	0.25 hrs	\$0.00	
55-8100	Controller	0.25 hrs	0.25 hrs	\$0.00	
55-8150	Tecumseh Compressor	0.25 hrs	1.50 hrs	\$18.00	\$18 allowance for R134a; 1.5 hours included system evacuation time
55-8400	Generator Start Capacitor	0.25 hrs	0.50 hrs	\$0.00	
55-8413	Compressor Assembly	0.25 hrs	1.50 hrs	\$18.00	\$18 allowance for R134a; 1.5 hours included system evacuation time
55-8413-R	Compressor Assembly (Reman)	0.25 hrs	1.50 hrs	\$18.00	\$18 allowance for R134a; 1.5 hours included system evacuation time
55-8414	Controller Assembly (Keypad Style)	0.25 hrs	0.25 hrs	\$0.00	
55-8418	Dynasys Starter	0.50 hrs	1.50 hrs	\$0.00	
DSB-04262010	Service Bulletin DSB-04262010	0.00 hrs	0.50 hrs	\$0.00	